## **DESCRIPTION OF ILLICIT DISCHARGE**

## Worksheet

Instructions: Describe illicit discharges that were exposed to storm water

District 1

Description of Exposed Significant Material	Date of Exposure	Location	Action Taken
Bad Drainage	6/13/2011	Rice Road @ Thrill Hill	Improved drainage, cut ditches
Cross Drain Collapsed	6/13/2011	Woods Rd. @ dead end	Replaced Cross Drain
Bad Drainage	6/13/2011	Meadow Hills @ Entrance of North Old Canton Rd.	Rechannelized drain
Cross Drain Stopped up	6/13/2011	Strong Rd. @ approx. N. Old Canton Rd.	Replaced Cross Drain
Cross Drain Collapsed	6/13/2011	Dover Lane	Replaced Cross Drain
	I		